

JOBSITE ATTIRE

HARD HAT

Must meet OSHA 1926.100 standard.

SAFETY GLASSES

Must meet ANSI Z87.1 requirements.

EAR PLUGS

Must be worn when sound levels are exceeded.

SHIRT

Must have sleeves minimum of 4".

SAFETY VEST

Must meet ANSI Class II requirements.

GLOVES

Worn when handling materials. Use the proper glove for the task.

RESPIRATOR

Worn to protect against harmful airborne contaminants.

FACE SHIELD

Must be worn when operations present potential eye & face injury.

FULL LENGTH PANTS

BOOTS WITH HARD SOLES